

Installation Instructions


Extra Parts Bag for Single & Two Stage Gas Furnaces

It is necessary to vent this furnace according to the methods described in the Venting Requirement section of the furnace installation instructions. Please refer to the installation instructions for proper usage of the listed parts. Before permanently installing these components, it is recommended you dry-fit them first to ensure proper fit and alignment with other vent pipes.

EXTRA PARTS BAG FOR *G7 / *GC2 (SC, SL, SM, TL) FURNACES - P/N M0001112		
PART NUMBER	DESCRIPTION	QUANTITY
600364	#10, 1-1/4" Inducer Screw	1
606286	Hose Clamp	1
631758	Strain Relief Bushing	1
632261	3 Amp Fuse	1
663894	Connector, Union, 1/2" x 3/8"	1
663989	1/2" Barb x 3/4" NPTF Connector	1
664633	Inlet Air Finish Flange	1
664886	14.5" Drain Tube	1
689089	7/8" ID Gas Line Grommet	1
690074	2-1/4" ID Vent Grommet	1
690094	3/4" ID Condensate Grommet	1
690101	3-1/2" OD Finish Flange Gasket	1

Table 1. Extra Parts Bag Contents - M0001112

2" PVC Pipe from
Inline Drain Assembly
(Not Included)



EXTRA PARTS BAG FOR *G7 / *GC2 (SD, TC, MQ) FURNACES - P/N M0001113		
PART NUMBER	DESCRIPTION	QUANTITY
600364	#10, 1-1/4" Inducer Screw	1
606286	Hose Clamp	1
631758	Strain Relief Bushing	1
632261	3 Amp Fuse	1
663115	2" PVC Tee	1
663894	Connector, Union, 1/2" x 3/8"	1
663989	1/2" Barb x 3/4" NPTF Connector	1
664633	Inlet Air Finish Flange	1
664659	PVC Trap	1
664886	14.5" Drain Tube	1
689089	7/8" ID Gas Line Grommet	1
690074	2-1/4" ID Vent Grommet	1
690094	3/4" ID Condensate Grommet	1
690101	3-1/2" OD Finish Flange Gasket	1

Table 2. Extra Parts Bag Contents - M0001113

